ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0387, W0383, W0232, W0385, W0093, W0024, W0095, W

Street Name
Mani Lyt 1st Main Rd, 1st Crs, NA, 8th Crs Gramatana, 15th Crs, Om Shakthi Lyt 2nd Crs, 16th Crs, Om

Significant Landmark
Singapura Paradise and Surrounding Roads

Segment No.
11/C-W0387/S080640

Total Length (m)
819.02

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	118.25	77.542979	13.082797	77.543065	13.083862	W0091	W0095
2	195.29	77.540325	13.079727	77.541260	13.081235	W0097	W0018
3	95.97	77.540004	13.078890	77.540289	13.079709	W0038	W0097
4	118.25	77.542979	13.082797	77.543065	13.083862	W0034	W0024
5	195.29	77.540325	13.079727	77.541260	13.081235	SWD	W0048
6	95.97	77.540004	13.078890	77.540289	13.079709	WO232	SWD

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Road and Drains at Singapura Paradise and Surrounding Roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zon

Sanctioned Estimated Amount (Rs.)
3000000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Road and Drains at Singapura Paradise and Surrounding Roads in ward no 11 (Kuvempunagara) Vidyaranayapura Sub-Division Yelahanka zone

Job No. / Work Code
011-16-000003

Work Order No.
BBMP/EE/BTP/WO/41/2016-17

Work Order Date
26/05/2016

Period of Extention
90 DAYS

Defect Liability Period From
26/05/2016

Defect Liability Period To
25/05/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B B UMESHA		0.00

Phone No.	E-Mail ID
9886213563	

Field Inspection Details

Number of Trees	Any Other Information	Name
0		SURESH

Date of Inspection	Remarks
14/09/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0387, W0383, W0232, W0385,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	14/09/2016	14/10/2016	COMPLETED
SE	VASU K M	14/09/2016	14/10/2016	COMPLETED
EE	YARAPPA REDDY	14/09/2016	14/10/2016	COMPLETED
AEE	SHIVAKUMAR	14/09/2016	14/10/2016	COMPLETED
AE	SURESH	14/09/2016	14/10/2016	COMPLETED
AE	SURESH	14/09/2016	14/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0387, W0383, W0232, W0385,